

# ***CORROCOAT CASPIAN***

## **CASE STUDY**

<b><u>Customer:</u></b>	Eurasian Foods, Karagandy
<b><u>Equipment:</u></b>	Tanks for storage of sulfuric acid V-35m3
<b><u>Location:</u></b>	Karaganda, Kazakhstan
<b><u>Dates:</u></b>	February 20 – March 05 2019
<b><u>Environment:</u></b>	sulfuric acid 98% concentration
<b><u>Surface area:</u></b>	128 m2
<b><u>Coating:</u></b>	Corrothane XT - 1000 microns

### **Work site (temperatures at nights fell as low as minus 20C):**




### **Storage tanks from the outside:**



# ***CORROCOAT CASPIAN***

## **Grit blasting and vacuum cleaning:**



## **Quality control after grit blasting:**



## **Application of Corrothane XT (spray and hand):**



# ***CORROCOAT CASPIAN***

## **Application works completed:**



## **Final inspection:**

