

CORROCOAT CASPIAN

CASE STUDY

Customer: Karazhanbasmunai

Equipment: Oil separators V-200m3

Location: Karazhanbas oilfield, Mangistau region, Kazakhstan

Dates: May 06 – June 06 2019

Environment: oil and formation water with high salt level and sand

Coating: Corroglass 600 (for corrosion pit repair), Polyglass VEF at 1000 microns

Work place:



CORROCOAT CASPIAN

Grit blasting:



Blasted surface quality control:



Repair of corrosion pits:



CORROCOAT CASPIAN

After application of Polyglass VEF at 1000 microns:



Final inspection:

