


# ***CORROCOAT CASPIAN***


## **CASE STUDY**

<b><u>Customer:</u></b>	Oil and gas condensate company
<b><u>Equipment:</u></b>	2 process vessels
<b><u>Environment:</u></b>	Gas condensate, crude oil
<b><u>The job:</u></b>	Internal lining of 2 process vessels with aggressive environment
<b><u>Location of the job:</u></b>	Karachaganak gas condensate field (Western Kazakhstan)
<b><u>Coating:</u></b>	Corrothane XT
<b><u>Date:</u></b>	September 2017

### **Surface preparation:**




### **Application of Corrothane XT:**



# ***CORROCOAT CASPIAN***

## **Stripe coating / hand application of Corrothane XT:**



## **Refurbished separators:**

